
Windmill-Parts.com 940 597-7735

1898 MODEL PUMPING AERMOTOR.



This illustration shows the parts of the Pumping Aermotor with roller bearings as made in the year 1898. Some of the parts used on the first mills of this model, and then discontinued, are not shown here. Among these are 207 threaded, replaced by 307 bolted; 209, replaced by 309; 225, threaded pump rod angle, replaced by 337, flatted and bolted. When either 207 or 225 are with a state of the parts are no longer furnished.

307 and 237, as the old parts are no longer furnished.

940 597157 1358 which are peculiar to this style of mill are numbered from 201 to 372.