


REPAIR LIST FOR MONITOR VANELESS MILLS



Give name and symbol of each part when ordering.

Windmill-Parts.com

Name of Part	940 597-7735 10 Ft. L Style				12 Ft. M Style			
	Sym- bol	Price	Weight		Sym- bol	Price	Weight	
			Lb.	Oz.			Lb.	Oz.
Upper tower casting - steel tr	C1	\$.80	3	10	H1	\$	6	
Upper tower casting - wood tr	L1	2.35	4	11	M1W	2.35	4	8
Lower tower casting - steel tr	C2	3.50	3	5	M2	3.85	7	
Lower tower casting - wood tr	L2	1.75	3	10	M2W		4	8
Bottom turntable	C4	2.00	3		M5A	2.00	5	
Balance weight	L4A		44		M4		65	
Bronze bushing for pitman	L5A	1.50		3	M5	2.00		8
Bronze bushing for main cstg	WC6	.65		5	M6	1.40	1	
Pitman guide L 7 discontinued, use L7A, L8A, L9A & L100A in place.								
Pitman guide	L7A	5.85	6	8				
Crank	L8	7.70	7	8	M8	9.70	11	
Crank	L8A	7.70	6	8				
Wrist pin & nut for L9	GZ8	1.05		10				
Pitman & bushing	L9	3.05	3	8	M9	7.70	6	
Pitman & bushing	L9A	4.90	3	11	M9A		6	8
Hub with shaft	E10B	23.00	32		M10			
Outer sleeve - top half	L11A	1.50	2		M11	1.75	3	5
Outer sleeve - top half	L11B	1.50	2					
Outer sleeve - bottom half	L12A		3	8	M12	2.60	6	6

Name of Part	10 Ft. L Style				12 Ft. M Style			
	Sym- bol	Price	Weight		Sym- bol	Price	Weight	
			Lb.	Oz.			Lb.	Oz.
Outer sleeve - bottom half	L12B	\$ 2.90	3	8		\$13.40		
Sleeve complete		9.70	7	8		5.85	12	8
Inner sleeve	L13A	3.85	2		M13	.80	3	
Sheave	E14	.80	10		L14			13
Shipper spider	L15A		9					
Shipper spider	L15C	6.80	9					
Piston eye	L16	1.52	1	8	M16	2.60	2	11
Pump pole socket	K17	1.05	1	2	M17	1.75	3	3
Swivel slide	K18	1.40	2		M18	2.00	3	13
Swivel slide guide	K19	1.20	2		M19	2.00	3	8
Grease plunger	E21	.35		3	E21	.35		3
Rim casting - right	L23	1.05	1		L23	1.05	1	
Rim casting - left & set screw	L24	1.20	1		L24	1.20	1	
Section rod eye & nut	L25	1.40	1	3	L25	1.40	1	3
Wheel spoke	L26	1.75	5	3	M26		7	
Section lever	L28	1.75	2		L28	1.75	2	
Gear cover	L29	4.70	6	5	M29		7	
Ratchet grease cup for L9A	L33	.70	5		L33	.70		5
Plain grease cup for L15A	L34	.35	5		L34	.35		5
Plain grease cup for L3A	L35	.80	6		L35	.80		6
Pitman guide pin	L52	.80	13		M52	1.75	1	13
Pitman pin	L53	.80	11		M53	1.50	1	11
Piston rod & nut	K54	2.35	4	11	J54	3.50	7	
Piston rod & 17		3.40	5	14		6.50	10	3
Sheave pin	E59	.35		2	M59			2
Sleeve bail	L60	.80		6	M60			5
Balance weight arm	L63		10	5	M63		14	10
Balance weight arm	L63A		15					
Balance weight arm truss rod	L64		2	6	M64		3	2
Balance weight arm truss rod	L64A		2					
Wheel spoke brace - round	L65	.80	1	2	M65		1	5
Wheel spoke brace - flat	L65A		1					
Shipper rod	L66A	1.20	1	8	M66A	1.20	1	8
Section hinge rod	L67A	1.20	1	8	L67A	1.20	1	8
Connecting rod - 13 to 28	L69A			8	M69			13
Sector casting hinge pin	L71A	.70		3	M71A			15
Swivel complete with chain	L79B	5.40	2	13	M79	6.20	4	
Governor spring	L82		2		L82		2	
Governor spring	L82A	3.85	2		L82A	3.85	2	
Governor spring clip	L83			6	L83			6
Governor spring extension	L84A	.80		10	L84A	.80		10
Lock washer for L67A	L88			2	L88			2
Lock washer for L25	L89			2	L89			2
Sleeve shield	L90		1		L90		1	
Cap screw for L90	L91			2	L91			2
Wrist pin with nut for L9A	L100	2.20	1	3	M100	3.85	2	5
Wrist pin with nut for M9A				3	M100A			5
Chill race for top turntable	L101	1.50	1		M101		3	13
Steel race for top turntable	L102	1.05		8	M102			10
Cover for top turntable	L104	1.20	1	8	M104		2	5
Sail	L124		1		M124		1	
Rim - short	L126	.80	1		M126		1	
Rim - long	L128	1.50	2		M128		2	
COMPLETE PARTS								
One section complete	L501-1	16.30	15		M501-1		15	
Pump couplet assembly	WC120	1.60		2	WC120	1.60		2